

A Happy New Year!
恭贺新禧!
¡ Feliz Año Nuevo!



Dear valued customers !!!

We had various incidents not only in Japan but also around the world last year.

We faced "Cost increase of raw materials" at the beginning, and then "Demand decrease" and "Issue of exchange rate" caused by "Financial crisis" started from U.S. subprime loan problem.

We are forecasting that we will have harder time in the market this year as well.

However, we are ready for doing our best especially about quality control as manufacturer very seriously.

We would appreciate your continuous great support of **New-Era** products this year.



Yours Sincerely,

New-Era Co., Ltd.

北村伸雄

Nobuo Kitamura, President



NEW PRODUCTS NP-171

Illustration	Ref. No.	Application	On Sale
IVR-5009 12V 	8-94239099-0 (126000-0270) ALTERNATOR 12V60A 8-94231307-0 (100211-0581) ALTERNATOR 12V65A 1-54519937-2 (100211-0991)	ISUZU FARGO PIAZZA TRACTOR JR120/130 (4ZB1) (G200) (D3200)	Jan.'09 '81~'87 '81~'88 '84~'93
IVR-5010 12V 	(126000-7160) (126000-1760) (126000-1130) ALTERNATOR 12V100A 3544118 3544118-7 3544119 (100211-8620) (100211-8630) 1398327 (100211-8370)	VOLVO 940 740	Jan.'09 '90~'97 '91~'92

<http://www.newera.co.jp/>

New-Era Co., Ltd.



Illustration	Ref. No.	Application	On Sale
D-093 12V 	27375-6340 (021580-2260) (021580-2250) ALTERNATOR 12V50A 23700KA430 (100211-3970) 23700KA630 (100211-9440) 12V55A 27040-64050 (100213-0451) 27040-64051 (100213-0710) 27040-64052 (100213-0740) 27040-78200-71 (100213-1200) 31100-PD1-034 (100211-1212) 27060-63040 (100211-1231) 31100-PE0-921 (100211-1261) 31100-PE0-003 (100211-1271) 31100-PC0-923 (100211-1311) 27060-10010 (100211-1341) 27060-10060 (100211-2300) 27060-87702 (100211-2330) 27060-63041 (100211-2380) 27060-10011 (100211-3500) 27060-10061 (100211-3540) 27060-55020 (100211-3560) 27060-10090 (100211-3610) 27060-72150 (100211-3680) 27060-11050 (100211-3740) 27060-70310 (100211-3831)	TOYOTA MR2 AW11 (3A-LU) '84~'84 COROLLA, SPRINTER AE85,AE86, (3A-LU, 4A-GEU, '83~'89 AE91 5A-F) CORSA, COROLLA II EL31 (3E) '86~'90 CORONA CT141,CT170 (1S-ELU/LU) '83~'85,'87~'92 STARLET NP70, EP71, (2E-ELU/LU/TELU, '84~'92 NP80, EP82 1N, 4E-F/FE) EP85 CARINA AT171 (5A-F, 3E) '88~'90 CROWN S130,140,150 (1G-FE) '89~'99 MASTER ACE (2C, 2Y-U) '85~'87 LITEACE, TOWNACE (2C, 1C, 2Y-U, '85~'90 3Y-U) HIACE, REGIUS (3Y, 3Y-P/J, 2Y, '87~'93,'00~'03 1RZ) DAIHATSU CHARADE G11, G100 (CB50/51, HC-E) '86~'88,'90~'93 APPLAUSE (HD) '89~'93 DELTA WIDE (1C, 2C) '85~'90 HONDA CITY AA, GA (ER) '82~'96 CIVIC EF (EV, EW, ZC, '83~'89 B15B, D15B) BALLADE AJ, AK (EV,EW) '83~'87 QUINT AV, DA1/2 (ZC,EW) '85~'89 CONCERTO MA (ZC) '88~'92 CR-X EF (ZC, B15B, D15B) '87~'89 SUBARU (FUJI) SAMBER (EN07Y) '90~'95	Jan.'09
D-038 12V 	B675-18-W60 (A860T27070) ALTERNATOR 12V60A B675-18-300C (A002T05772)	MAZDA/FORD ETUDE BFMP, BFSP (B5,B6) '86~'95 CAPELLA (626) GD6P (B6) '86~'95 CAPELLA CARGO GV6V (B6) '86~'95 FAMILIA BFMP, BFMR, (B3, B5, B6 ,E3, E5) '86~'95 BFSP BFSR, BFTP, '86~'95 BF3V BF5V, BF6M, '86~'95 BW3W BW5W, BWMR '86~'95 RASER BF3VF, BF5VF, (E3,E5,B6) '86~'95 BE6ME	Jan.'09